STANDARD OPERATING PROCEDURES

DIVISION OF COMPARATIVE MEDICINE UNIVERSITY OF SOUTH FLORIDA

SOP#: 1117.3 Date Issued: 11/00 Date Revised: 7/20 Page 1 of 2

TITLE: Refrigerator/Freezer Thermometer Use SCOPE: Research and Animal Care Personnel

RESPONSIBILITY: Facility Manager, All Animal Program Personnel

PURPOSE: To Outline the Proper Procedures for Use and Maintenance of the

Refrigerator/Freezer Thermometer

I. PURPOSE

1. This procedure outlines the use and maintenance of a refrigerator/freezer thermometer used to monitor refrigerator/freezer temperature within the animal facilities.

II. RESPONSIBILITY

- 1. It is the responsibility of the Facility Manager to ensure that equipment is appropriately cleaned, maintained in good working order, and available for research personnel as requested.
- It is the responsibility of the veterinary professional, administrative, and managerial staff to ensure that all research and technical staff using this equipment are adequately trained and experienced to perform hygrometer/thermometer determinations.

III. EQUIPMENT USE

- 1. Before using, slide open battery cover located on back of unit and insert one AA battery. Replace cover.
- Slide the switch on back of unit to ⁰C for Celsius.
- 3. Slide alarm to off. Refer to instruction booklet if necessary to use the alarm mode.
- 4. Insert external sensor probe jack into outlet on side of unit.
- 5. To mount unit, apply Velcro® to back of thermometer unit and to the desired location outside the refrigerator unit.
- 6. Place liquid vial/probe inside the refrigerator in a location it will not get broken.
- Normal display mode shows the current, minimum, and maximum readings at the same time. Record these temperatures on CMDC 020 Refrigerator/Freezer Temperature Log.

SOP# 1117.3 Traceable Refrigerator-Freezer Thermometer Effective 7/20 Page 2 of 2

8. Press Memory clear button to reset the MAX/MIN temperatures.

IV. MAINTENANCE

- 1. Clean unit by wiping with a mild disinfectant and soft cloth.
- 2. Replace AA alkaline battery when digits flash, there is no display, or display is faint.
- 3. Abnormal readings not corrected by battery replacement should be promptly reported to the Facility Manager.
- 4. Annually recertify and label the unit in accordance with **SOP #1115 Thermometer/Hygrometer Certification.**
- 4. Any additional maintenance/service should be performed by authorized personnel.

V. REFERENCES

Manufacturer's Manual.

Approved:	Date: